

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, January 31, 2019	Project Contact:	Brian Clauto
Spread: Franklin County MP246 St13012-12993, St1303013038, MP248 St13117	Spread H	Weather (Wet/Dry/Rain):	Wet
STAGE OF CONSTRUCTI	ON: (Check all that apply)		
Clearing	Rough Grading	Trench Excavation	Pipe Assembly, Testing & Installation
Backfilling and Grade	e Restoration Final Grading	& Stabilization	Other: dormant
		Yes No N/A	
	d and implemented in accordance with the nt control plan and stormwater management		
Are all control meas condition in accorda applicable, manufac	ures properly maintained in effective oper ince with good engineering practices and, sturer specifications?	rating where	
3 Areas of offsite sedi	ment deposition were observed?		
Comments: MP 246.07 St#12993+00 CFS triple stack at sump requires maintenance. Recommended Corrective Action: Maintain all controls per the approved plan and annual standards and specs.			
Deadline:Within 24hr notification The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project. Inspector Signature:			



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date:Thursday, January 31, 2019

 Fig. 1 MP 246.07 St#12993+00 CFS triple stack at sump requires maintenance.



Fig. 2 Near St#12299 tree fallen on ECD waiting on NPS approval.



Fig. 3 Near St#13023 slopes have been stabilized.



Fig. 4 Near St13038 slopes have been stabilized.

